

Parts Drawing Code(s)	Steinel Item#	Description
1+2+3	04011	Set housing shells HG2300
2	04012	Cover plate for power cord
3	04013	Housing screws-5pcs.
4	04014	Outlet tube w/o heating element
5	04015	Screw M 4x16 stainless steel plus bushing
7	04017	Rubber ring
8+9	35013	Power cord w/strain relief
10	04002	Terminal for wire connection
11	04001	Plastic hold down clip for power cord
12	04003	Monitoring electronics
13	04004	Switch left, red
14	04005	Switch right, blue
15	04006	Motor
17	04007	Motor resistor
16	354111	Heating element w/outlet tube

